



MONTAGEANLEITUNG

INSTRUCTIONS DE MONTAGE


ASSEMBLY INSTRUCTIONS

MONTAGEAANWIJZING




980671
























60 min





Ø5 mm



102	8	 3 x 15 mm	210	4		408	4	 4 x 9 mm
113	2		220	4		503	2	 A
122	2		320	8	 6,3 x 50 mm	509	2	 B
181	12		351	8	 3,5 x 15 mm	511	2	 C
190	8	 8 x 30 mm	358	4	 4,0 x 35 mm	603	8	 1,2 x 20 mm
193	4	 5 x 40 mm	370	1	 4 x 15 mm	741	1	 8 x 51 mm
204	1		371	1	 6 x 60 mm	742	1	


1.

2x




- 509 (B)
- 511 (C)

2.



3.



4.

12x

181

2x

113

210

351

1

2

2x

210

351

Warning symbol: exclamation mark inside a triangle.

5.

3

1

7

3

7,5 mm

14,5 mm

7,5 mm

14,5 mm

14,5 mm


7,5 mm

320


4x

RS 08.05.2008 980671 3 / 6


6.




7.




8.




9.




10.




11.





8x



102

